## Issues

| # | Project | Tracker | Category | Status | Priority | Subject | Assignee | Updated |
|---|---------|---------|----------|--------|----------|---------|----------|---------|
| 10923 | pfSense | Bug | Hardware / Drivers | Resolved | Normal | Update ixl Driver on pfSense 2.5.0 to bring back Intel X710-T2L/T4L support that was present on version 2.4.5-P1. | | 10/05/2020 08:39 AM |