

## Issues

| #    | Project | Tracker | Category   | Status   | Priority | Subject                                                                            | Assignee       | Updated             |
|------|---------|---------|------------|----------|----------|------------------------------------------------------------------------------------|----------------|---------------------|
| 3846 | pfSense | Bug     | Interfaces | Resolved | Normal   | Adding interface for new VLAN selects active WAN VIP address breaking connectivity | Renato Botelho | 10/06/2014 02:29 PM |