

Issues

#	Project	Tracker	Category	Status	Priority	Subject	Assignee	Updated
10923	pfSense	Bug	Hardware / Drivers	Resolved	Normal	Update ixl Driver on pfSense 2.5.0 to bring back Intel X710-T2L/T4L support that was present on version 2.4.5-P1.		10/05/2020 08:39 AM