

pfSense - Feature #7137

Add support for Sierra MC7455

01/18/2017 05:45 PM - Daniel Ziehmayer

Status:	Duplicate	Start date:	01/18/2017
Priority:	Normal	Due date:	
Assignee:		% Done:	0%
Category:		Estimated time:	0.00 hour
Target version:		Release Notes:	
Plus Target Version:			
Description			
please add support for Sierra Wireless MC7455 card, thx			
Details:			
usbconfig -u 1 -a 4 dump_device_desc			
ugen1.4: <Sierra Wireless MC7455 Qualcomm Snapdragon X7 LTE-A Sierra Wireless, Incorporated> at, cfg=0 md=HOST spd=HIGH (480Mbps) pwr=ON (500mA)			
<pre>bLength = 0x0012 bDescriptorType = 0x0001 bcdUSB = 0x0210 bDeviceClass = 0x0000 <Probed by interface class>; bDeviceSubClass = 0x0000 bDeviceProtocol = 0x0000 bMaxPacketSize0 = 0x0040 idVendor = 0x1199 idProduct = 0x9071 bcdDevice = 0x0006 iManufacturer = 0x0001 <Sierra Wireless, Incorporated>; iProduct = 0x0002 <Sierra Wireless MC7455 Qualcomm Snapdragon X7 LTE-A>; iSerialNumber = 0x0003 <LQ63120537021007>; bNumConfigurations = 0x0001</pre>			

History

#1 - 03/02/2017 02:42 PM - Daniel Ziehmayer

Now it works

see: <https://redmine.pfsense.org/issues/6832> (the same idProduct)

#2 - 03/02/2017 04:00 PM - Renato Botelho

- Status changed from New to Duplicate

Duplicate of [#6832](#)